



OLTENS





Molle

1. Install the distributor shown in the diagram at the correct height on the wall using screws and dowels as shown in the diagram. The distributor should be installed at a height of 1.5 m above the floor.




2. Remove the screw from the wall mounting bracket (for the sliding bar) and mount the bracket at the correct height on the wall as shown in the diagram.







3. Install the bar with the headset holder using the mounting element according to the instructions.



4. Loosen the shower holder, connect the rod to the switch, tighten the shower holder and install the cap on the mounting element.




5. Connect a 0.6 m flexible hose to the distributor and connect the other end to the water inlet.



6. Connect the 1.5 m shower hose to the switch and shower head, then adjust the position of the shower holder. The shower head can be adjusted to a height of 1.5 m.


7. Install the rain shower head.



8. After installation, check the water connection and the tightness of the installed components of the set.

Handle facing upwards – water flows through the rain shower.

Turn the handle 90 degrees to switch to the hand shower.



Notes on the installation instructions:

- Do not disassemble the assembled parts, as they have been assembled and checked before leaving the factory.
- To avoid damaging the thermostatic battery, flush the system with water before installation to remove solid contaminants such as sand, stone, and sediment.
- Before installation, make sure that there are no hidden cables or pipes in the wall where you intend to drill
- After installation, make sure that all connections are tight and there are no leaks.

Technical information

Maximum pressure **0,1 MPa - 0,6 MPa**

Recommended pressure **0,2 MPa - 0,5 MPa**

Maximum temperature of hot water **85°C**

Recommended temperature of hot water **55°C - 65°C**

Check whether the installation of hot and cold water was done correctly.

Care and maintenance

Flush with clean water and wipe with a dry, soft cloth.

For heavier deposits, it is recommended to use special tap cleaning agents, preferably professional Oltens products from the NanoCare and NanoShine series.

Never use agents containing alcohol, disinfectants, solvents and strong bases.

Never clean the surface of the tap with rough cloths or cleaning agents containing abrasive materials and acids..

